

Director, Environmental Health & Safety 577 Western Avenue P.O. Box 1630 Westfield, Massachusetts 01086-1630

> Tel: 413.572.5209 Fax: 413.572.5486

HOTWORK PERMIT PROGRAM

In accordance with the requirements of the Massachusetts Fire Prevention Regulations 527 CMR 39 and OSHA 29 CFR 1910.252 a Hot Work Permit is required for the following activities: brazing, cutting, heating, soldering, welding or similar type work. The intent of this program is to prevent injury and loss of property from fire when using heat-producing equipment such as soldering tools, heat guns, oxy-fuel gas and electric arc cutting and welding equipment.

Hot Work will be permitted in approved areas and will be issued to both Westfield State University staff and contractors by the Office of Environmental Health and Safety or a designee of that office. On occasion, with the approval of the office of EH&S, a blanket permit can be granted for a long duration project and ongoing work. A blanket permit can also be considered for a series of small jobs related to one project on the campus.

PERMIT:

- 1. The area(s) shall be inspected by EH&S or a qualified Westfield State employee.
- 2. They type of hot work must be approved for the project being performed.
- 3. Containers/pipes must be properly cleaned/purged, and then inspected.
- 4. All flammable and combustible materials must be removed from the Hot Work area.
- 5. Floor and wall openings (within 35") shall be covered or sealed to prevent possible spread of fire.
- 6. Fire detection and suppression equipment shall remain operational at all times, unless otherwise protected or approved by the Department of Public Safety or the Office of EH&S.
- 7. Fire extinguishers of proper size and type shall be located within 25 ft. of Hot Work area.
- 8. Hot Work equipment such as hoses, leads, gas cylinders, and torches shall be properly maintained and secured as not to prevent loss or exposure.

- 9. Personal Protective Equipment (PPE) is required and shall be worn. Examples of the PPE include but are not limited to: clothing, face shields, goggles, gloves, and head and foot protection.
- 10. EH&S safety hazards such as asbestos, stored chemicals, solvents and other hazards including electrical, fire, heat, and ventilation should be evaluated prior to HOT WORK.
- 11. A fire watch (not less than ½ hour shall be performed for each HOT WORK permit issued.
- 12. Bags for smoke detectors shall be supplied and installed by the contractor when necessary.
- 13. Permanent or portable curtains and screens must be used if persons are or could be exposed to the direct or reflected radiation.
- 14. Exhaust ventilation has been provided or has been determined to be sufficient.

Fire Watcher(s):

The university reserves the right to require a separate person to perform a fire watch.

- 1. The fire-watcher shall have the proper size and type of a fully charged fire extinguisher within 25 ft.
- 2. The fire-watcher shall be properly trained in the proper use and limitations of the fire extinguisher.
- 3. The fire-watcher shall be familiar with the proper procedures for activating a fire alarm and for the notification to the Department of Public Safety/Westfield Fire Department.
- 4. The fire watch shall be maintained for at least 1 hour after the Hot Work is completed. (1/2 hour if approved by the Office of EH&S)

Gas Storage and Transportation:

- 1. All cylinders must be secured at all times by either an approved chain strap.
- 2. All cylinders must have a cap or a regulator in place at all times.
- 3. All cylinders must be stored, transported and used in an upright position.
- 4. All cylinders and attached equipment must be free of damage and leaks
- 5. All cylinders must be clearly labeled

In the event of an emergency contact the Office of Public Safety at 413 572-5262 If any questions, please contact the Office of Environmental Health and Safety at 413 572-5209

January 2013

WESTFIELD STATE UNIVERSITY – HOT WORK PERMIT

BUILDING:	ROOM/AREA:	DATE:
	TOR:	
	FIRE WATCHER:	
	END DATE:TIME RAN	
Hot Work Type	Work Area/Equipment	Container/Pipe Contents
Brazing Welding	□Exterior □Interior	(past or present material)
Cutting - Arc - Air Arc - MIG	- Building Structure	
	- Building Fixture	Cleaned Yes No
- Mechanical - Oxy-Fue - Oxy-Fuel - TIG	5.4	Purged Yes No
- Plasma	- Fume Hood	How Cleaned/Purged:
☐ Heating	- Pipe - Tank	
☐ Soldering	- Valve - other:	Date Cleaned/Purged://
	- voive - other:	EH&S requested Yes No
Fire Hazards	Health & Safety Issues	Cylinder, Equipment & Hose
Combustibles	Asbestos Present Yes No	Gases Used
Covered	Chemicals/Cleaners Present Yes No	☐ Butane
☐ Removed ☐ None Present	Name:	Oxy-Acetylene
Flammables	14	☐ Propane
Covered	Confined Space Yes No	ofher:
Removed	Monitor required Yes No Permit required Yes No	
None Present	Permit required Yes No Electrical Hazards Yes No	Cylinder Storage and Use
Floor / Wall Openings	GFCI required Yes No	Away from ignition source Yes No
☐ Covered		Cap or regulator in place □ Yes□No
☐ Not Applicable	Heat Stress Precautions Yes No	Free of damage and leaks Tes No
	Heat Stress Precautions Yes No Work/Rest ratio/	Labeled properly
Detection/Suppression	PPE Required Yes No	Outside of building/space Tyes No
Detectors Sprinklers	Clothing	Secured w/chain or strap
☐ Beam ☐ Operational	Face Protection Foot Protection	Upright storage/transport □ Yes□No
☐ Heat ☐ Non-Oper	Hand Protection Head Protection Respiratory	Hose, Leads and Torch
☐ Smoke ☐ Not Present	☐ Negative Pressure ☐ Positive Pressure	Connections tight
☐ Bagged		Flash arrestor in place
Disconnected Fire Watch	Other:	Free of damage and leaks Tyss No.
Evtinguishor Yes	Shields or Curtains Required Yes No	Additional Comments:
CO2 Dry Chem	Ventiliation Required Yes No	
THOSE TRAW	☐ Negative Pressure ☐ Positive Pressure	
□N/A □ hr		
(signatures required below)		
PERSON AUTHORIZING HOT WORK:		
Fire watch was maintained for at least one hour at close of Hot Work		

Copies of this form will be provided to the Contractor, Area Supervisor and the Office of EH&S

Director, Environmental Health & Safety:_